

# Fluke 50S and 50D Thermometers

## Specifications

<b>Temperature accuracy:</b>	K-type [ 0.1% + 0.7 °C (1.3 °F)] J-type [ 0.1% + 0.8 °C (1.4 °F)]
<b>Temperature range:</b>	K-type -200 °C to 1370 °C (-328 °F to 2498 °F) J-type -200 °C to 760 °C (-328 °F to 1400 °F)
<b>Display resolution:</b>	0.1 °C (0.2 °F) over full range

### General

<b>Unit weight:</b>	280 g (10 oz)
<b>Dimensions: (without holster)</b>	16.6 cm L x 7.5 cm W x 2.8 cm D (6.6 in L x 3.0 in W x 1.1 in D)
<b>Battery</b>	9V battery
<b>Battery life</b>	800 hours typical
<b>Certification</b>	CE, CSA